


MONTAGEANLEITUNG

-  MONTAGEANLEITUNG
-  ASSEMBLY INSTRUCTION
-  DE INSTRUCTIE VAN DE ASSEMBLAGE
-  ISTRUZIONE DI MONTAGGIO
-  INSTRUCCIÓN DE ASAMBLEA
-  INSTRUCTION DE MONTAGE
-  NÁVOD K MONTÁŽI
-  MONTERINGSANVISNING

-  MONTAJ TALIMATI
-  ASENUSOHJE
-  BRUGSANVISNING
-  BRUKSANVISNING
-  UPUTE ZA MONTAŽU
-  NAVODILA ZA MONTAŽU
-  SZERELÉSI ÚTMUTATÓ
-  INSTRUCTIUNI DE MONTAJ



Version 16.6

Modell-Nr.

70180

ART.-NR. FRONT KORPUS

70182



Silber

70187



Silber

70186



Schwarz
(RAL 9005)

Friedrich Küpper
Friedrich-Küpper-Weg
54570 Berlingen
Deutschland

Telefon +49 (0) 65 91 - 95 42 0
Telefax +49 (0) 65 91 - 95 42 17
E-Mail info@friedrich-kuepper.de
Internet www.friedrich-kuepper.de

EINZELTEILE / PIECES

4× **B**



800 mm × 200 mm

Art.-Nr. E0310 (Silber/silver)
Art.-Nr. E0311 (Schwarz/black)

1× **D**



850 mm × 200 mm

Art.-Nr. E0312 (Silber/silver)
Art.-Nr. E0313 (Schwarz/black)

4× **E**



600 mm × 200 mm

Art.-Nr. E0315 (Silber/silver)
Art.-Nr. E0316 (Schwarz/black)

2× **G**



600 mm × 180 mm

Art.-Nr. E0323 (Silber/silver)
Art.-Nr. E0324 (Schwarz/black)

4× **J**



595 mm × 400 mm

Art.-Nr. E0331 (Silber/silver)

2× **K**



595 mm × 400 mm

Art.-Nr. E0334 (Silber/silver)

4× **M**



560 mm × 375 mm

Art.-Nr. E0344 (Silber/silver)
Art.-Nr. E0341 (Rot/red)
Art.-Nr. E0343 (Blau/blue)

4× **P**



393 mm × 138 mm

Art.-Nr. E0365 (Schwarz/black)

12× **Q**



130 mm × 100 mm × 50 mm

Art.-Nr. E0367 (Rot/red)
Art.-Nr. E0368 (Grau/grey)

24× **R**




130 mm × 130 mm × 70 mm

Art.-Nr. E0371 (Rot/red)
Art.-Nr. E0372 (Grau/grey)

BEUTELINHALT / BAG CONTENT

 38× M5 × 10 mm Art.-Nr. E0286	 38× ø 5,3 mm Art.-Nr. E0287	 38× M5 Art.-Nr. E0288	 4× Art.-Nr. E0292	 4× Art.-Nr. E0291	 8× 4,5 × 60 mm Art.-Nr. E0374
 8× E6 × 30 mm Art.-Nr. E0375	 8× 15 × 15 mm Art.-Nr. E0376	 8× Art.-Nr. E0298			

BENÖTIGTES WERKZEUG / NEEDED TOOLS

1  PH 2 × 100	2  SW 8	3  6 mm
4 	7 	8 

1.



2.


2 × M5

2 × M5 × 10

2 × 5,3 mm

② SW8

① PH 2 × 100



3.




4.

1 × M5 1 × M5 × 10 1 × 5,3 mm ② SW8 ① PH 2 × 100



5.




6.

2 × M5 2 × M5 × 10 2 × 5,3 mm ② SW8 ① PH 2 × 100




WIEDERHOLEN SIE DIE SCHRITTE 1–6 / REPEAT STEPS 1–6

7.



8.



9.

2 × M5

2 × M5 × 10

2 × 5,3 mm

② SW8

① PH2 × 100



10.


2 × M5

2 × M5 × 10


2 × 5,3 mm

② SW8

① PH2 × 100



11.



12.


3 × M5

3 × M5 × 10


3 × 5,3 mm

② SW8


① PH2 × 100



13.



14.




15.

2 × M5 2 × M5 × 10 2 × 5,3 mm ② SW8 ① PH2×100



16.

2 × M5 2 × M5 × 10 2 × 5,3 mm ② SW8 ① PH2×100



17.



18.

3 × M5 3 × M5 × 10 3 × 5,3 mm ② SW8 ① PH2×100



19.

2 × M5

2 × M5 × 10

2 × 5,3 mm

②  SW8

①  PH 2 × 100



20.

2 × M5

2 × M5 × 10

2 × 5,3 mm

②  SW8

①  PH 2 × 100



21.

2 × M5

2 × M5 × 10

2 × 5,3 mm

②  SW8


①  PH 2 × 100



22.



23.



24.


4 × M5

4 × M5 × 10

4 × 5,3 mm

②  SW8

①  PH 2 × 100



25.

②  SW8

①  PH 2 × 100




26.  8x

27.



28.



29.



4×



4×



30.




31.



32.




A.



B.



C.



Modell-Nr.

70180